

CENTRAL INTELLIGENCE AGENCY

**REPORT NO.**

## **INFORMATION REPORT**

CD NO.

25X1A

COUNTRY USSR

DATE DISTR. 17 Dec 1953

SUBJECT Soviet Industrial Bank's Breakdown of  
Construction Financing

NO. OF PAGES 1

PLACE  
ACQUIRED  25X1A

NO. OF ENCLS.  
(LISTED BELOW)

25X1 DATE ACQUIRED  25X1

SUPPLEMENT TO  
REPORT NO.

DATE (of Info)

THIS IS UNEVALUATED INFORMATION

25X1X

1. The Industrial Bank of the USSR, with its numerous branches throughout the country, maintained close control over funds used to finance construction or improvement of factories. The Bank's representatives inspected plants under construction. They could decrease funds for certain activities if they felt too much had been requested.
  2. The following breakdown of inspection by a Bank representative indicates how detailed it was and how close a control was maintained of financing. A typical factory building under construction was inspected, as to quality of work, progress, and cost, by means of the following breakdown:
    - (a) earth excavation
    - (b) foundations (concrete, etc)
    - (c) walls
    - (d) roofs
    - (e) floors
    - (f) windows and doors
    - (g) electric and plumbing facilities, and

The Industrial Bank furnished funds for each of the above categories. It did not provide one sum to cover complete construction of a factory building. By this means the Bank retained its close control of construction financing.

-end-

**—BY SUBJECT & AREA CODES—**

718-1-2N1

**CLASSIFICATION CONFIDENTIAL**

---

**DISTRIBUTION**

25X1